# National Institute of Speech and Hearing (NISH): Comprehensive Accessibility Audit Report 2018

Audit conducted by,

Ms. Anjlee Agarwal & Mr. Debratha Chakravarthy

Samarthyam, National Centre for Accessible Environments, New Delhi

14th - 16th November 2018

Report prepared by,

Centre for Assistive Technology & Innovation (CATI) & New Initiatives (NI),

NISH

26 December 2018

### Introduction

Mr Sandeep, ISL trainer was sick and slept off in the sick room. As he did not wake up even after repeated banging of door, messages, phone calls, he was left alone in NISH, Next day while asking for a solution, he suggested a cheap one. A vibrator under the cot and a switch outside the room. Thus accessibility was made one of the agendas of 12th IQAC held on May, 17, 2018. It was decided to entrust Samarthyam, National Centre for Accessible Environments, a National Level organisation for undertaking the process. Thus NISH initiated the process of conducting accessibility audit. Accessibility is one of the major thrust areas of the RPwd Act 2016. The two days extensive programme include Accessibility audit of the campus, creating awareness on Universal Accessibility, Interactive sessions among the Accessible consultants, NISH Personnels and Students.

## Scope of the Audit

The audit will look into the following aspects:

- Universal Accessibility Features
- Safety & Security measures
- Gender Perspective
- Age friendly accessible environment

### **Objectives of the Audit**

- To evaluate the existing infrastructure, connectivity, mobility issues, mode of communication, Pedestrian Accessibilities and Safety & security measures in and around the campus
- To evaluate the usage of existing amenities
- To make recommendations for improving the existing situation

# Floor areas of all the 3 buildings

- 1 6539 m2
- 2 4571.89 m2
- 3 769.32 m2

# Methodology

Look through the eyes of all users!

Holistic Approach- Walk-in-audit

Conducted Walk audit which is facilitated walk with an interdisciplinary Team consisting of External Audit Consultants, Engineers, Admin Personnel, Social Worker, Documenting personnel, Person with Hearing Impairment and one interpreter.

Locati on	Problem	Recommendatio ns	Solution	Status, Marked by
Fro	m Entrance to I	Marigold/Thejus		
Road outside NISH campu s	No traffic signal or zebra crossing.	Pedestrian-controlle d traffic signal, Signages indicating 'Disability-friendly zone'.	1. Installing Pedestrian-contr olled traffic signal, Signages indicating 'Disability-friendl y zone'	Soja  Statutory requirements?  Accident prone area  Speed breaker  Will make arrangement for Handrail and pathways frm dept.  Rate??  Traffic signal?will check with engineer
Entranc e to NISH: Photo 1 Photo 2	The slope is too steep. There are two levels, drainage openings.	There should be a single, gentle slope (1 in 15 max). No gaps and no level differences.  Tactile warning tiles before and after the pedestrian gate.	<ol> <li>Easing the gradient by providing cement and concrete.</li> <li>Place tactile warning tiles at 300 mm before and after the pedestrian gate.</li> </ol>	Provided  • Get permission from pwd for road?

AT	Μ	a
NI	Sŀ	1
ga	te	

- 1. Two unequal and high steps, with less tread width.
- 2. No ramp for wheelchair access.
- 1. A straight ramp will go on to the road. So, there are 2 options:
  - flooring and ramp
  - (2) OR L-shaped ramp (5 with a landing space of with hand-rails
- 2. Door should provide clear opening of 900mm minimum.
- 3. Markings on the glass panel needed at 900mm and 1500mm level to avoid ppl with low vision walking into
- 4. Tactile warning tiles at the

possible,

L-shaped ramp

is the better

option. Give landing space of

1.5x1.5m and

ramp with width

1.5m and slope

then extend

of 1:15

maximum. Ramp will go

beyond the

has to be

compound wall

of NISH, which

demolished and

reconstructed.

Continuous

ramp at two

hand-rails on

both sides of the

- (1) Lower ATM then provide
  - metre long, 1.5m wide) 1.5x1.5m,

beginning and end of ramp.

- 1. Since lowering Separate the ATM flooring estimate will not be
  - 2nd option is applicable L-shaped one

- levels 760mm and 900mm. 2. Door with clear opening of 900mm minimum.
- 3. Markings on the glass panel needed at 900mm and 1500mm level to avoid ppl with low vision walking into it.
- 4. Tactile warning tiles at 300mm at the beginning and end of ramp.
- 5. Steps to ATM landing space uniform risers of

			maximum 150mm and tread 300mm minimum. 50mm wide contrast color paint and tactile markings at the edge of each step.	
Accessi ble Car parking	1. Cars are parked close to the building wall security risk.  2. No accessible parking slots.	<ol> <li>Wheel stoppers at 1.2 m away from the wall.</li> <li>At least 2 accessible parking spaces for Thejas (next to the ramp) and 2 for Dhyan         <ol> <li>With road markings and signages</li> <li>Check guidelines for space between vehicles (aisle space for wheelchair)</li> </ol> </li> </ol>	1. Wheel stoppers at 1.2 m away from the building and also from the compound wall.  2. At least 2 accessible parking spaces for Thejas (next to the ramp) and 2 for Dhyan  a. With road markings and signages  b. Check guideline s for space between vehicles (aisle space for wheelcha ir)	done
Ramp to Marigol d from car parking Photo 1	<ol> <li>Too steep.</li> <li>The entrance to the ramp is not smooth.</li> <li>Projection tiles are not good</li> </ol>	<ol> <li>9m long ramp is needed.</li> <li>Broom finish at the starting of the ramp.</li> <li>Tactile warning tiles at begin and end</li> <li>Hand-rails</li> </ol>	<ul> <li>5. a 9m long ramp with anti-skid tiles is needed and broom finish at the starting of the ramp.</li> <li>6. Tactile warning tiles at 300mm in begin and end</li> <li>7. Hand-rails</li> </ul>	

	for ramp. 4. No hand-rails	(continuous and unobstructed) at 2 levels on both sides of the ramp. Check knuckle space. Ensure that hand-rail goes around the pillar and continues down the steps.	(continuous and unobstructed) at 2 levels on both sides of the ramp. Check knuckle space. Ensure that hand-rail goes around the pillar and continues down the steps.  8. Existing unequal steps will be modified as per these specifications - uniform risers of maximum 150mm and tread 300mm minimum. 50mm wide contrast color paint and tactile markings at the edge of each step.	
Ramp at side entranc e to Marigol d from car park	<ol> <li>No ramp now.</li> <li>Steps are unequal, no hand-rails</li> </ol>		<ol> <li>Ramp with hand-rails to be provided.</li> <li>Contrast color at the edge of the steps - yellow or terracotta colour paint</li> <li>Tactile warning tiles at the start and end</li> </ol>	
Pedestr ian path from Thejas to Dhyan	3. Manhole	<ol> <li>Use parking tiles         (Eg. from         Johnsons), not         the terracotta         ones for the         porch.</li> <li>The pedestrian         path has to be         1.5m at least.</li> <li>Manhole         shouldn't be on         the pedestrian         path. How to         avoid it? Start</li> </ol>	<ol> <li>Use parking tiles         (Eg. from Johnsons),         not the terracotta         ones for the porch.</li> <li>The pedestrian path         has to be 1.5m at         least.</li> <li>Manhole shouldn't         be on the pedestrian         path. Start ramp to         Dhyan entrance from         before the manhole         itself.</li> <li>Tactile guiding tiles,</li> </ol>	

	access. 4. No signs indicating Marigold/T hejas/Dhy an	ramp to Dhyan entrance from before the manhole itself.  4. Tactile guiding tiles, square junctions at the places that you have to turn and Signages to guide to different buildings.	square junctions at the places that you have to turn and braille-cum-text Signages to guide to different buildings.	
Dhyan entranc e  Dhyan existing Ramp way to Ramp 2. Dhyan	Very steep ramp (1:6 slope now) No ramp from Dhyan towards amruth	Need 6m long ramp.  Deviate path from before manhole and make the gentle slope, with continuous hand-rails on both sides. Hand-rail should go around the column/pillar.	1. Need 6m long ramp.  Deviate path from before manhole and make the gentle slope, with continuous hand-rails on both sides. Hand-rail should go around the column/pillar. 2. Steps to replace existing ramp in front of Dhyan	
Zebra-c rossing	Not accessible to wheelchair users or the ppl with visual impairment	Kerb ramp and tactile tiles are needed	Kerb ramp and tactile tiles as per specifications at the two zebra-crossings are needed.	
Thejas entranc e - ramps Photo 1 Photo 2	The 2 ramps in the front are too steep and dangerous.	<ol> <li>Remove the 2 ramps or cordon off the area.</li> <li>Ramp on the side - add overhead shelter. Alter ramp dimensions to fit guidelines. (1:15 slope)</li> <li>Tactile warning tiles before, after</li> </ol>	<ol> <li>Convert the existing 2 ramps in the front into steps.</li> <li>Existing ramp at the right side - ease the gradient. New ramp to be constructed on the left side to go towards Dhyan.</li> <li>Tactile warning tiles before, after ramp,</li> </ol>	

		ramp, after door and guiding tiles to the reception.	after door and guiding tiles to the reception.	
	Inside T	hejas		
Thejas -	Ground floor			
Inside Marigol d Photo 1 Photo 2 Photo 3: Podium stand height & Accessi bility Photo 2 Photo 3	No fire alarm/sprinkle rs. No signage to exit. No ramp to stage inside the hall No wheelchair-fri endly podium on stage( resolved) Very steep ramps to stage from green room	1. Dias height is 750mm. So a 12m ramp (minimum width 1.2m) is needed inside the hall. L-shaped with middle landing space (1.5m long after 9m of ramp). No hand-rails but with edge protection of around 100mm. Ramp can be fabricated and permanent (like in Orchid). TV can be shifted to the side of the dias - 2 TVs on both sides if needed. 2. Ramp on the left side from green room - put anti-skid mat. It is steep - someone has to assist to push the wheelchair. 3. Ramp on the right side from green room is dangerously steep. Replace it with platform lift.	<ol> <li>Ramp on the left side from green room - put anti-skid mat.</li> <li>Ramp on the right side from green room - replace it with platform lift.</li> <li>Ramp to dias in the front - from right side. 12m ramp (minimum width 1.2m) is needed inside the hall. L-shaped with middle landing space (1.5m long after 9m of ramp). No hand-rails but with edge protection of around 100mm.</li> <li>TV can be shifted to the side of the dias - 2 TVs on both sides.</li> <li>Fire alarms, sprinklers, signages to exit.</li> </ol>	
Outside Marigol d,		Directional     signages to toilet     and accessible	Directional signages     to toilet and     accessible toilet.	

Г	<u></u>
Thejas lobby Photo 1 Photo 2	toilet. Braille signage just outside the toilet.  2. Heights of switch panels in lobby should be lower (450-1000mm) in contrast color.  3. Courtyard edge stick a contrast color band.  4. Floor directory/tactile map  5. Cordon off the area under the staircase with plants/sculpture/g ate - to avoid people with visual impairment walking and hitting their head.  6. Need ramp at fire exit. (Extend landing, side ramp)  7. Relocate the fire extinguisher - obstruction on the way to fire exit.  8. Lower signages.
Toilets in ground floor Photo 1 Photo 2 Photo 3  Photo 3  1. Toilets inside greenroom are too small. 2. Toilets just outside Marigold - small for wheelchair users, Male and female toilets shouldn't be	<ol> <li>Toilets near         Marigold can be         called</li></ol>

	facing each other - most abuses happen there. Better if adjacent to each other.  3. 'Accessible toilet' outside BFA is too small for parallel or diagonal transfer from wheelchair. Existing grab bar is not useful - it just takes up more space.	washbasin height, grab-bars positioning, mirror height. 3. 1 child-friendly urinal in male toilet - at a lesser height 4. At least 1 urinal with grab bars for semi-ambulatory users	<ol> <li>1 child-friendly urinal in male toilet - at a lesser height</li> <li>At least 1 urinal with grab bars for semi-ambulatory users</li> </ol>
Steps to first floor	It's a guard-rail, not hand-rail.	<ol> <li>Tactile warning tiles</li> <li>Contrast edges</li> <li>Hand-rail - need two levels, unobstruct ed. 900mm level is there. Add one more at 760mm.</li> <li>We discussed about adding another hand-rail on the wall-side but that was deferred because it will decrease the operational width of the stairs.</li> </ol>	<ol> <li>Tactile warning tiles         300mm before steps.</li> <li>Contrast edges paint.</li> <li>Hand-rail - need two         levels,unobstructed.         900mm level is there.         Add one more at         760mm.</li> </ol>
Lift lobby	What is the     Fire lift'     signage	Add audio alert.     Lower control     panel and	Add audio alert.     Lower control panel     and telephone - mind

	doing there??  2. No audio alert in lift  3. Control panel is too high.  4. Floor level signs are not visible from the lift  5. Notice next to lift has too many instructions , is high.	telephone - mind highest operable point.  3. Remove the 'fire lift' signage.  4. Add floor level signs in front of each lift.  5. Notice next to lift - need bigger font, height to be lowered.	highest operable point.  3. Add floor level signs in front of each lift.  4. Notice next to lift - minimize instructions, need bigger font, height to be lowered.	
Tejas Recepa tion		<ol> <li>Tactile warning tiles in the front</li> <li>Glass cut-outs to pass things</li> <li>Contrast colour at table edge</li> <li>Signages</li> <li>Contrast colour band around pillars</li> </ol>	<ol> <li>Tactile warning tiles in the front</li> <li>Glass cut-outs to pass things</li> <li>Contrast colour at table edge</li> <li>Signages</li> <li>Contrast colour band around pillars</li> </ol>	
Thejas fi	irst floor			
Orchid- Hall Photo 1 Photo 2 Photo 3	No fire alarms Lights are very dim - only 33 lux. No door stoppers	<ol> <li>Need fire alarms.</li> <li>Improve lighting</li> <li>Add frosted glass to door, with two clear openings at 800mm and 1400mm.</li> <li>D-shaped door handles are more ergonomic than the knob.</li> </ol>	<ol> <li>Need fire alarms.</li> <li>Improve lighting. Need 500 lux level.</li> <li>Add frosted glass to door, with two clear openings at 800mm and 1400mm.</li> <li>D-shaped door handles are more ergonomic than the knob.</li> </ol>	
Lobby		1. Floor level	Floor level	

		signage can be closer to the stairs - for both staircases.  2. Tactile warning tiles before and after staircase.  3. Floor directory on every level.	signage can be closer to the stairs - for both staircases.  2. Tactile warning tiles before and after staircase.  3. Floor directory on every level.	
Admin Photo 1	Almirahs behind a seated person - risk of person getting trapped in case of an earthquake.	<ol> <li>Separate name boards for each of the admin with braille number system</li> <li>Guiding tactile cues on floor (like PVC mat in guest room) to every admin personnel</li> <li>Warning tiles at door</li> <li>Relocate almirahs.</li> <li>Contrast color at table edges.</li> </ol>	1. Separate name boards for each of the admin with braille 2. number system 3. Guiding tactile cues on floor (like PVC mat in guest room) to every admin personnel 4. Warning tiles at door 5. Relocate almirahs. 6. Contrast color at table edges.	
PT (Vikrant h's) room	Signages are scattered - eg: room number, name of the person, dept name etc Almirah blocking path to toilet	Order the signages vertically, at a lower level. Relocate almirah.	1. Order the signages vertically, at lower level. 2. Relocate almirah.	
Accessi ble toilet Photo 1 Photo 2 Photo 3 Photo 4	Accessible toilet is too small. Door hook for toilet door - not good.replace with latch.	There are two options:  1. Interchange accessible toilet with the ladies' washroom, just like in the ground floor. Problem is	In the existing accessible toilet:  1. relocate WC to the corner to make more space for wheelchair parallel or	

		there is a step at the entrance.  2. (Or) In the existing accessible toilet, relocate WC to the corner to make more space for wheelchair parallel or diagonal transfer. Also, shift washbasin to the opposite side. Remove existing grab bar. Add new grab bars (movable and L-shaped) as per the guidelines.	diagonal transfer.  2. shift washbasin to the opposite side.  3. Remove existing grab bar. Add new grab bars (movable and L-shaped) as per the guidelines.	
Thejas s	econd floor			
Staff room		Table edges - contrast color bands	Table edges - contrast color bands	
Notice board		Bigger fonts needed, too high for wheelchair-user to see	Follow specific font and font size.	
Classro oms for the deaf	Lighting issues. When lights switched off for slides, teacher's signing is not visible.	Add focus light on teacher.	Add focus light on teacher.	
Thejas third floor				
Sick room		Door to wash     area is not     needed.      For the entrance	<ol> <li>Door to the wash area is not needed.</li> <li>For the entrance door, frosted glass</li> </ol>	

		door, frosted glass with vision panel at two levels.  3. Two-way alert system: Switch outside the room, when pressed will set on the vibrator under the pillow as well as the flashing bulb. Switch near the bed, when pressed will activate buzzer and light alarm outside.  4. Boys' sick room - signage indicating 'nurse's station' to be changed.	with vision panel at two levels.  3. Two-way alert system: Switch outside the room, when pressed will set on the vibrator under the pillow as well as the flashing bulb. Switch near the bed, when pressed will activate buzzer and light alarm outside.  4. Boys' sick room - signage indicating 'nurse's station' to be changed.
Thejas F	ourth floor		
Compu ter lab Photo 1 Photo 2		Have an accessible system - with screen reader, adaptive keyboard, adaptive mouse etc.	Have an accessible system - with screen reader, adaptive keyboard, adaptive mouse etc.
Thejas F	ifth Floor		
Guest room (small)	Toilet is not accessible. Bed, table are too high (resolved)	<ol> <li>Separate area for washbasin is not needed. Remove the wall and make the toilet bigger.</li> <li>Door to toilet should be sliding or opening to outside.</li> <li>Relocate WC to where washbasin is now. Shower</li> </ol>	<ol> <li>Separate area for washbasin is not needed. Remove the wall and make the toilet bigger.</li> <li>Door to toilet should be sliding or opening to outside.</li> <li>Relocate WC to where washbasin is now. Shower area on the opposite end with a plastic chair and a</li> </ol>

		area on the opposite end with a plastic chair and a telephone shower (never a head shower!).  4. Add an emergency bell in toilet, that will buzz housekeeping/se curity cabin.  5. Bed must me 450mm high (same height of wheelchair), no sharp corners. (can cut legs/ have thinner mattress)  6. Switch panel must be next to bed. A switch activating audiovisual alarm outside room and in housekeeping/se curity. A switch outside the room activating an audiovisual+vibra tory alarm for the room resident.  7. Table must have more leg space underneath (670mm needed).	telephone shower (never a head shower!).  4. Add an emergency bell in toilet, that will buzz housekeeping/securit y cabin.  5. Round off the sharp corners in bed.  6. Switch panel must be next to bed. A switch activating audiovisual alarm outside room and in housekeeping/securit y. A switch outside the room activating an audiovisual+vibratory alarm for the room resident.  7. Table must have more leg space underneath (670mm needed).
Guest room (bigger suite)	Dining table is too high (resolved) No compatible plug for microwave.	Reduce height of dining table, bed, switch panels as per guidelines.     Alarm bells as specified above for the other	<ol> <li>Reduce height of switch panels as per guidelines. Alarm bells as specified above for the other guest room.</li> <li>Toilet area has to be</li> </ol>

	Toilet is not accessible.	2.	guest room. Toilet area has to be increased and made accessible as per guidelines. Remove the wall. Dressing table may not be needed.		increased and made accessible as per guidelines. Remove the wall. Dressing table may not be needed.	
Tulip halls Photo 2	No chair for a left-handed student. No accessible toilet on this floor for students taking exams. Wheelchair-fri endly podium	<ol> <li>3.</li> </ol>	wheelchair-friendl y podium needed. Accessible toilet in the side terrace area.	1. 2. 3.	Sm al mler, wheelchair-friendly podium needed. (resolved. Cost = Rs 9500) Accessible toilet in the side terrace area. A few chairs with desk hinge on the left side for left-handed students.	
Thejas 7	th floor					
Library Photo 1 Photo 2	Counter is not wheelchair-fri endly. Fonts on notices on book shelves have to be as per guidelines for people with visual impairment. More AT devices and softwares needed in library.	<ol> <li>3.</li> <li>5.</li> </ol>	be at 800mm height. Notice on book shelves - Use font size 14 with Sans serif or Arial or Helvetica. Emergency alarms are missing. Magnifier, vibrating alarms to be available. Software like Read & Write	1. 2. 3. 4. 5.	Counter has to be at 800mm height. Notice on book shelves - Use font size 14 with Sans serif or Arial or Helvetica. Emergency alarms are missing. Magnifier, vibrating alarms to be available. Software like Read & Write Gold/Sonocent etc should be available. Accessible PC for browsing the e-catalogue. Books on accessibility should be kept - Eg:	

		7. Books on accessibility should be kept - Eg: IRC103-2012 (Inclusive pedestrian facilities), National building code, Manual on universal accessibility for roads and streets	IRC103-2012 (Inclusive pedestrian facilities), National building code, Manual on universal accessibility for roads and streets	
Outside	Thejas	<b>.</b>		
Benche s	Not deaf-friendly	Curved benches, with shelter on top.	3 Curved benches, with shelter on top.	
Dhyan g	round floor			
Dhyan recepti on Photo 1 Photo 2	Counter is partially accessible. Poor lighting	<ol> <li>Counter needs         knee clearance         for         wheelchair-users.         Height on the         other side is         1.2m - it has to         be 1m maximum.</li> <li>More lights are         needed.</li> <li>Floor directory is         good. Change         font as per         specification to         make it better.</li> </ol>	<ol> <li>Counter needs knee clearance for wheelchair-users.         Height on the other side is 1.2m - it has to be 1m maximum.</li> <li>More lights are needed.</li> <li>Floor directory - Change font as per specification to make it better.</li> </ol>	
Stairca se just before EIP Photo 1	Uneven height steps, hand-rails not continuous	<ol> <li>Contrast color the edges of stairs.</li> <li>Continuous hand-rails on the other side.</li> </ol>	<ol> <li>Contrast color the edges of stairs.</li> <li>Continuous hand-rails on the other side.</li> </ol>	
Biometr ic ID	Too high	For an employee who uses wheelchair, at least one of		

		the biometric devices has to be at a lower height.		
EIP Photo 1 Photo 2 Photo 3	Walkway is too narrow. Steps to the park are too high. Might not be perceived by kids with visual or sensory issues. Neetha reports one such accident.	<ol> <li>Corridor can't be less than 1.8m. Replace thick coir mats with thin rubber mats. Can shoes rack be narrower?</li> <li>Different options:         <ul> <li>Either fill in the play area and make it same level - can be too expensive.</li> <li>Cordon off with hand-rails on the second step and having only two entry points into the play area.</li> <li>Best option - extend the corridor upto the first step and add one more step.</li> </ul> </li> </ol>	1. extend the corridor upto the first step and add one more step. Cordon off with hand-rails on the second step and having only two entry points into the play area.  2. Replace thick coir mats with thin rubber mats.  3. shoes rack can be narrower	
Ear mould lab Entranc e photo 1 Photo 2	door is narrow, fridge near entrance - no path for wheelchair-us ers	Relocate fridge.	Relocate fridge.	
All doors to rooms	Vision panel is too high for wheelchair users.	Vision panels at two heights	Vision panels at two heights	

Photo 1				
All corridor s	Thick coir mats are trip hazards. Complaints/su ggestions box protruding in Dhyan first and second floors.	<ol> <li>Replace coir mats with thin rubber mats.</li> <li>Relocate complaints box.</li> </ol>	<ol> <li>Replace coir mats         with thin rubber         mats.</li> <li>Relocate complaints         box.</li> </ol>	
Childre n's library Entranc e photo 1 Inside table arrange ments Photo 3	alignment of tables near entrance can be dangerous for kids running	Align tables against the wall	Align tables against the wall	
Sensor y lab	Therapy ladder/steps handrails are too high for kids	Lower hand-rails at 600-700mm max. They are at 870mm now.	Lower hand-rails at 600-700mm max in therapy ladder.	
Toilet	Toilet is not accessible. Not enough space.	Use space from the sensory park outside to construct a new toilet 2x2.2m	Use space from the sensory park outside to construct a new toilet 2x2.2m	
Creche Photo 1 Toilet	Creche is very nice and accessible.	Have toilet door handles at kids' height also. no Latches inside.	Have toilet door handles at kids' height also. no Latches inside.	
Ramp to top floors Photo 1	No middle landing at a gap of 9m Too narrow	Add hand-rails at last level and also to cordon off the dead pocket.	Add hand-rails at last level and also to cordon off the dead pocket.	

Photo 2 Photo 3	(<2m) Hand-rails missing in the last level Dead pocket High-risk place for abuse	<ol> <li>Add more CCTVs.</li> <li>Add emergency switches.</li> </ol>	<ol> <li>Anti-skid tiles</li> <li>Tactile warning tiles</li> <li>Add more CCTVs.</li> <li>Add emergency switches.</li> </ol>	
Lift?			Lift?	
Dhyan fi	rst floor			
Floor director y	make it more accessible	Add symbols.	Add symbols.	
CP unit	Too narrow doorway.	Relocate table near door. Adjust door hinge - relocate it further to make the door wider.	Relocate table near door. Adjust door hinge - relocate it further to make the door wider.	
Speech diagno stics labs	Very narrow door entrances (780mm) Doorstep not wheelchair-fri endly	Increase height of the door and lower the step. Can door be wider (900m at least)?	Increase height of the door and lower the step. Door to be wider (900m at least).	
Accessi ble toilet	Not available	Raise one more level from the to-be-constructed accessible toilet on the ground floor.	Raise one more level from the to-be-constructed accessible toilet on the ground floor.	
Fire exit	Not available			
Dhyan second floor				
Daffodil	Dias is too small	Dias is not needed	Dias is not needed	
Outside Dhyan				

Path from Dhyan to Amruth Photo 1 Photo 3	No ramp from Dhyan towards Amruth Too steep ramps at entrance and exit of Amruth. Windows opening on ramp.	2. Entrance to Amruth - extend ramp to road with no level difference. Add hand-rails. Extend landing at Amruth and then ramp. (otherwise	<ol> <li>Ramp from Dhyan towards path near pool to be added.</li> <li>Entrance to Amruth extend ramp to road with no level difference. Add hand-rails. Extend landing at Amruth and then ramp. (otherwise curved ramp will need landing space)</li> <li>Exit from Amruth extend ramp to footpath. Close the windows permanently. Add hand-rails</li> </ol>	
Amruth Accessi ble toilet	Not available	Add one outside the washing area.	New accessible toilet outside wash basin area to be constructed.	
Univers al design cantee n Photo 1		<ol> <li>Tactile         pavers till         food counter</li> <li>Menu in         braille</li> <li>Round         tables - easy         to sign and         eat.</li> <li>A couple of         low tables,         kid chairs</li> </ol>	<ol> <li>Tactile pavers till food counter</li> <li>Menu in braille</li> <li>Round tables - easy to sign and eat.</li> <li>A couple of low tables, kid chairs</li> </ol>	